side of an unknown

vehicle on the middle

lane as car driver lost control due to over speed. Page 1 of 5

Ambulance, RPV

NATIONAL HIGHWAYS AUTHORITY OF INDIA

Name of PIU's Jaipur

(1) Stretch: NH 8 (Gurgaon - Kotputli - Jaipur)

(2) Stretch Chainage: Km 42.7 to 273

(3) State: Haryana & Rajasthan

(4) District: Gurgaon, Rewari, Alwar, Jaipur

(5) Police Station

08.06.18

7:00 AM Rural

196.150/RHS

Near Hotel

3

Khirki Daula, Manesar, Bilaspur, Dharuhera, Kasaula, Bawal, Shahjahnpur, Nimrana, Behror, Paniyala, Kotputli, Pragpura, Shahpura, Manoharpur, Chandwaji, Harmara, Vishwakarma, Murlipura,

Accident Data

											Acc	ideni Data									
N	ational	Highwa	yay No.	:	8															From (08.06.18 to 14.06.18
					A		В	C	D	E	F	G	H		I	No. of Affec	ted Pers	sons	N6		
S No	Da	te Acc	ime of ecident M/PM)	Accident Location		ation	Nature of Accident	Classfication of Accident	Causes	Road Features	Road Condition	Intersection Type and Control	Weather Condition	Vehicle Responsible	Fatal	Grievous	Minor	Non Injured	No. of animals killed if any	Help provided by Ambulance/ Patrol Vehicle	Remarks
1	08.06	5.18 12:5	:55 AM	Rural	138.250/RHS	Open Area	3	1	2	4	1	-	1	Rear trailer NoRJ52-GA- 0925	1	-	,	-	-	RPV	A trailer hit on rear side of another trailer on slow lane as trailer driver lost control due to over speed.
2	08.06	5.18 1:10	10 AM	Urban	175.000/LHS	In Market	8 (Multiple Pile up)	4	4A	4	2	-	1	Trailer container No RJ09-GA-7185	-	-	-	Yes	-	RPV	A Multiple pile up accrued between trailer container, innova car & truck on the slow lane due to trailer container driver fell asleep.
33	08.06	5.18 5:4	41 AM	Urban	133.600/RHS	On Flyover	8 (Multiple Pile up)	4	2	4	1	-	1	Trailer Container No- TN-21-AJ- 9670	-	-	-	Yes	-	RPV	A multiple pileup collision accident occurred between a trailer container, tractor trolley (loaded with sand) and another tractor trolley on slow lane due to over speed by trailer driver. Resulted trolley overturned on mid lane and sand spread on the road and trailer container jumped and hit to median MBCB and stand on LHS fast lane.
4	08.00	5.18 5:50	56 AM	Rural	171.450/RHS	Open Area	1	4	2	4	1	-	1	Eicher Canter No-HR-55-N- 6779	-	-	-	Yes	-	Ambulance	An Eicher container overturned on slow lane as its driver lost control due to over speed.
5	08.00	6:30	30 AM	Rural	059.960/LHS	In Market	8 (Single Vehicle)	4	2	4	1	-	1	Eicher Canter No.–HR55-N- 4811	-	-	-	Yes	-	RPV	An Eicher canter hit to height barrier as Eicher canter driver lost control due to over speed.
																					A Wagonr car hit on rear

3

2

Wagonr Car No.-DL-9C-S-

Г				A		В	C	D	E	F	G	Н		I	No. of Affec	ted Pers	sons	No. of	Help provided by Ambulance/ Patrol Vehicle	Remarks
S N		Time of Accident (AM/PM)		Accident Loca	ation	Nature of Accident	Classfication of Accident	Causes	Road Features	Road Condition	Intersection Type and Control	Weather Condition	Vehicle Responsible	Fatal	Grievous	Minor	Non Injured	animals killed if any		
7	08.06.18	3 7:40 AM	Rural	082.960/RHS	Open Area	3	3	2	4	1	-	1	Trailer No HR38-X-9009	-	-	2	-	-	RPV	A trailer (loaded with concrete) hit on rear side of a maruti container on the fast lane as trailer driver lost control due to over speed.
8	08.06.18	8:15 AM	Rural	169.560/RHS	Near Hotel	3	2	2	4	1	-	1	Trailer No.–RJ- 52-GA-6139	-	1	-	-	·	RPV	A trailer hit on rear side of tractor trolley (loaded with bricks) on the slow lane as trailer driver lost control due to over speed. Resulted trailer hit to roadside MBCB and jumped on out of soft shoulder and tractor trolley overturned on the slow lane.
g	08.06.18	9:20 AM	Rural	080.880/RHS	Near Hotel	3	4	2	4	1	-	1	Tata canter NoHR66-A- 6227	-	-	-	Yes	1	RPV	A tata canter hit on rear side of an unknown vehicle on the slow lane as tata canter driver lost control due to over speed.
1	08.06.18	3 10:40 AM	Urban	267.500/LHS	In Market	3	4	2	4	1	-	1	Truck No RJ14-GF-7178	-	-	-	Yes	-	RPV	A truck hit on rear side of a trailer (loaded with marble) on the slow lane as truck driver lost control due to over speed.
1	08.06.18	3 12:45 PM	Rural	136.550/RHS	Near Village	3	3	2	4	1	-	1	Truck Container No.–HR-61-D- 1409	-	-	1	-	-	RPV	A truck container hit on rear side of a trailer on the middle & slow lane as truck driver lost control due to over speed.
1:	08.06.18	3 4:00 PM	Rural	127.420/RHS	Open Area	3	4	2	4	1	-	1	Eicher canter No-GJ-15-XX- 1668	-	-	-	Yes	-	RPV	An Eicher canter hit on rear side of a dumper on the slow lane as Eicher canter driver lost control due to over speed and dumper ran-away from spot.
1	08.06.18	7:55 PM	Rural	150.200/LHS	Near Petrol Station	6	3	2	4	1	-	3	Motorcycle No- MP-34-MF- 0908	-	-	1	-	-	Ambulance	A motorcycle skidded on the service road as its rider lost control due to over speed.
1	09.06.18	3 1:32 AM	Rural	082.900/RHS	Open Area	3	4	2	4	1	-	1	Scorpio car No- RJ23-UB-0095	-	-	-	Yes	-	RPV	A Scorpio car jumped from RHS to LHS through median strip & hit with unknown vehicle on the fast lane due to over speed.
1:	09.06.18	3 1:45 AM	Rural	111.800/LHS	Open Area	3	4	2	4	1	-	1	Trailer No- RJ01-GB-3697	-	-	-	Yes	-	Ambulance	A Trailer hit on rear side of a maruti container on the fast lane as trailer driver lost control due to over speed.

				Α		В	С	D	E	F	G	Н		N	No. of Affec	ted Pers	ons		of.	
S		Time of Accident (AM/PM)		Accident Loca	ation	Nature of Accident	Classfication of Accident	Causes	Road Features	Road Condition	Intersection Type and Control	Weather Condition	Vehicle Responsible	Fatal	Grievous	Minor	Non Injured	No. of animals killed if any	Help provided by Ambulance/ Patrol Vehicle	Remarks
16	09.06.18	4:15 AM	Rural	170.100/LHS	Open Area	3	4	4A	4	1	-	1	Tata 1109 No- UP-14-ET- 4575	-	-	-	Yes	,	RPV	A tata 1109 hit on rear side of a pickup (loaded with fodder) on hard shoulder as tata 1109 driver lost control due to fell asleep. Resulted pickup overturned on side drain and fodder spread on hard shoulder and service lane.
17	09.06.18	5:30 AM	Rural	100.500/RHS	Open Area	3	4	2	4	1	-	1	Trailer No-HR- 55-W-1023	•	-	-	Yes	,	RPV	A trailer (loaded with wood) hit on rear side of a cruiser car on fast lane, as trailer driver lost control due to over speed by trailer driver. Resulted trailer overturned on mid, fast, median & LHS fast lane and car stand on soft shoulder.
18	09.06.18	9:20 AM	Rural	223.650/RHS	On Flyover	8 (Single Vehicle)	3	4A	4	2	-	1	Pick up No – RJ-14-GG- 4899	1	-	1	-	ı	RPV	A pick up hit to NJB on the slow lane as pickup driver lost control due to fell asleep.
19	09.06.18	7:50 PM	Urban	134.600/RHS	In Market	8 (Single Vehicle)	4	4A	4	1	3	1	Trailer No-RJ- 32-GA-5876	-	-	-	Yes	-	RPV	A trailer (cement bags loaded) hit to MBCB on the median due to fell asleep.
20	09.06.18	7:55 PM	Rural	235.100/RHS	Open Area	3	2	2	4	1	-	1	Unknown vehicle No-N/A (Ran-away)	-	1	1	-	-	Ambulance	A speeding unknown vehicle hit on rear side of a motorcycle on the slow lane.
2*	09.06.18	11:15 PM	Urban	263.500/RHS	Open Area	8 (Multiple Pile up)	2	2	4	1	-	1	Trailer No- HR46-E-1437	-	1	1	-	-	Ambulance, RPV	A Trailer hit on rear side of truck & truck hit on rear side of unknown vehicle on the middle lane due to over speed.
22	10.06.18	5:15 AM	Rural	221.350/RHS	Open Area	1	4	2	4	1	-	1	Tanker No-RJ- 47-GA-0290	-	-	-	Yes	-	RPV	A tanker (loaded with mustered oil) overturned on mid & fast lane as its driver lost control due to over speed. Resulted oil spread on the road.
23	11.06.18	2:05 AM	Rural	210.800/LHS	Toll Plaza Area	8 (Single Vehicle)	3	4A	4	1	-	1	Swift Dzire car NoRJ02-CA- 6684	-	-	1	-	-	Ambulance	A Swift Dzire car hit to toll plaza guard on VIP lane due to negligent driving.
24	11.06.18	5:10 AM	Rural	183.630/LHS	Open Area	3	4	2	4	1	-	1	Ertiga car No UP82-T-6110	-	-	-	Yes	-	RPV	A Ertiga car hit to rear side of a unknown vehicle on the slow lane as car driver lost control due to over speed.
25	11.06.18	5:10 AM	Rural	245.050/RHS	Open Area	3	4	2	4	1	-	1	Trailer No.RJ52-GA- 0939	-	-	-	Yes	-	RPV	A trailer hit to rear side of a truck container on the slow lane as trailer driver lost control due to over speed.

					A		В	C	D	E	F	G	Н		I	No. of Affect	ted Pers	ons			
S		ate A	Time of Accident AM/PM)		Accident Loca	ation	Nature of Accident	Classfication of Accident	Causes	Road Features	Road Condition	Intersection Type and Control	Weather Condition	Vehicle Responsible				N	No. of animals killed if any	Help provided by Ambulance/ Patrol Vehicle	Remarks
2	5 11.0	06.18	5:55 AM	Urban	153.240/RHS	Open Area	1	4	4A	4	1	-	1	Eicher canter No.GJ15-YY- 8379	-	-	-	Yes	-	Ambulance	An Eicher canter overturned on the slow land middle lane due to fell asleep.
2	7 11.0	06.18	9:30 AM	Rural	076.280/RHS	Open Area	1	4	4A	4	2	-	1	Tanker No-GJ- 12-Au-8309	-	-	-	Yes	-	RPV	A tanker (loaded with chemical) overturned onto out of soft shoulder as its driver lost control due to fell asleep.
2	3 11.0	06.18 1	12:50 PM	Rural	232.400/LHS	Open Area	6	3	2	4	1	-	1	Motorcycle No- RJ-49-SA- 5176	-	-	1	-	-	Ambulance, RPV	A motorcycle skidded on slow lane as its rider lost control due to over speed.
2	9 11.0	06.18 2	2:25 PM	Rural	184.600/LHS	Open Area	3	4	4A	4	1	-	1	Swift Dzire car No-RJ-14-LC- 2496	-	-	-	Yes	-	Ambulance	A swift Dzire car hit on rear side of a truck on the fast lane as car driver lost control due to negligent driving.
30) 11.0	06.18	7:05 PM	Rural	151.500/RHS	Open Area	3	4	2	4	1	-	1	Ritz car No-RJ- 18-CB-4229	-	-	-	Yes	-	Ambulance, RPV	A Ritz car hit on rear side of a trailer on the slow lane as car driver lost control due to over speed.
3	1 11.0	06.18	7:08 PM	Rural	152.100/RHS	Open Area	3	3	2	4	1	-	1	Motorcycle No- RJ-02-FS- 4015	-	-	1	-	-	Ambulance	A motorcycle hit on rear side of a cement bulker tanker on the slow lane as motorcycle rider lost control due to over speed.
3:	2 11.0	06.18	7:46 PM	Rural	148.400/RHS	Open Area	3	3	2	4	1	-	1	Unknown vehicle No- (Ran-away)	1	-	1	-	-	Ambulance	A speeding unknown vehicle hit on rear side of a motorcycle on the service road.
3:	3 12.0	06.18	3:05 AM	Rural	130.480/RHS	Open Area	3	4	2	4	1	-	1	Tanker No.GJ02-XX- 6540	-	-	-	Yes	1	RPV	A tanker (loaded with milk) hit to rear side of a trailer on the slow lane as tanker driver lost control due to over speed. Resulted trailer jumped on side drain.
34	1 12.0	06.18	3:25 AM	Rural	060.100/RHS	In Market	8 (Multiple Pile up)	2	2	4	1	-	1	Tata-1109 No. DL-1L-AA- 7214	-	1	1	-	-	Ambulance, RPV	A multiple pile up accident tata-1109 hit to rear side of unknown vehicle and after tanker hit to rear side tata-1109 one by one hit on the slow lane due to over speed.
3:	5 12.0	06.18	5:10 AM	Urban	267.300/RHS	Open Area	3	4	2	4	1	-	1	Truck No RJ14-GJ-2111	,	-	1	Yes	-	RPV	A truck hit on rear side of an unknown vehicle as truck driver lost control due to over speed.
3	6 12.0	06.18	9:30 AM	Rural	141.400/RHS	Open Area	8 (Single Vehicle)	4	2	4	1	-	1	Truck Container No- HR-55-S-7811	-	-	-	Yes	-	RPV	A truck container jumped onto out of soft shoulder as its driver lost control due to over speed.

				A		В	С	D	E	F	G	Н		ľ	No. of Affec	ted Pers	ons	N. C		
S. No.	Date	Time of Accident (AM/PM)		Accident Loca	ation	Nature of Accident	Classfication of Accident	Concoc	Road Condition	Intersection Type and Control	Weather Condition	Vehicle Responsible	Fatal	Grievous	Minor	Non Injured	No. of animals killed if any	Help provided by Ambulance/ Patrol Vehicle	Remarks	
37	12.06.18	10:24 PM	Urban	132.950/RHS	Open Area	3	3	2	4	1	-	1	Dumper No GJ21-V-1165	-	-	1	-	-	RPV	A dumper hit on rear side of a Private bus on the slow lane as dumper driver lost control due to over speed.
38	13.06.18	3:15 AM	Rural	183.300/RHS	On Flyover	3	4	2	4	1	-	1	Truck container No- NL01-N-7544	-	-	1	Yes	-	RPV	A truck container hit on rear side of a truck on the slow lane as truck container lost due to over speed.
39	13.06.18	4:35 AM	Rural	146.400/LHS	Near Village	3	4	2	4	1	-	1	Dumper No- HR47-C-2490	-	-	-	Yes	-	Ambulance	A dumper hit on rear side of an Eicher canter on the fast lane as dumper driver lost control due to over speed.
40	13.06.18	5:45 AM	Rural	143.850/RHS	Open Area	1	4	5A	4	1	-	1	Eicher canter No-DL1-LY- 4003	-	-	1	Yes	-	Ambulance, RPV	An Eicher canter overturned on the slow lane due to tyre burst.
41	14.06.18	2:30 AM	Rural	179.000/LHS	Open Area	3	3	2	4	1	-	1	Truck No RJ42-GA-0573	-	-	1	-,	-	Ambulance, RPV	A truck hit to rear side of a trailer on the slow lane as truck driver lost control due to over speed.
42	14.06.18	5:55 AM	Urban	253.600/LHS	On Flyover	3	2	2	4	1	-	1	Trailer container No HR55-AC- 0744	-	2	-	-	-	RPV	A Trailer container hit on rear side of a trailer on the middle & slow lane as trailer driver due to over speed.
43	14.06.18	10:30 AM	Rural	176.200/LHS	Open Area	3	3	2	4	1	-	1	Swift Car No- HR-27-E-7657	-	-	1	-	-	Ambulance, RPV	A swift Dzire car hit on rear side of a maruti container on slow lane as car driver lost control due to over speed.
44	14.06.18	11:08 AM	Rural	150.900/LHS	Near Village	6	3	2	4	1	-	1	Motorcycle No. RJ02-SA-5345	-	-	1	-	-	Ambulance	A motorcycle skidded on service lane as its driver lost control due to over speed.
							TOTAL							1	6	17	25	0		

Legends:

- A Urban/Rural and Details of Surrounding Landuse
- B 1. Overturning 2. Head on collision 3. Rear end Collision 4. Collision Brush/Sideswipe 5. Right Angled Collision 6. Skidding 7. Right Turned Collision 8. Others (Pl. Specify)
- C 1. Fatal 2. Grievous injury 3. Minor Injured 4. Non-injury
- D 1. Drunken 2. Overspeeding 3. Vehicle out of Control 4. Fault of driver of motorvehicle/driver of other vehicle/Cyclist/ Pedestrian /Passenger
- 5. Defect in mechanical condition of motor vehicle/Road Condition 6. Other (Specify)
- E 1. Single lane 2. Two lanes 3. Three lanes or more without central divider (median) 4. Four lanes or more with central divider
- F 1. Straight Road 2. Slight Curve 3. Sharp Curve 4. Flat Road 5. Gentle Road 6. Steep incline 7. Hump 8. Dip
- G 1. T-Junction 2. Y-Junction 3. Four arm junction 4. Staggered Junction 5. Junction with more than 4 arms 6. Roundabout junction 7. Manned rail crossing 8. Unmanned rail crossing
- H 1. Fine 2. Mist/Fog 3. Cloudy 4. Light Rain 5. Heavy Rain 6. Hail Steer 7. Snow 8. Strong Wind 9. Dust Storm 10. Very Hot 11. Very Cold 12. Other extraordinary weather condition (specify)